


2

1

| ITEM NO. | PART NUMBER | DESCRIPTION                     | QTY. |
|----------|-------------|---------------------------------|------|
| 1        | SL 1974     | DIAPHRAM SEAL ASM VITON         | 1    |
| 2        | SP 1975     | DIAPHRAM SPRING                 | 1    |
| 3        | SP 1979     | PLUNGER SPRING                  | 1    |
| 4        | PLGR.6978   | 1-1/4"L PLUNGER WITH VITON SEAT | 1    |
| 5        | OR 1976     | O-RING VITON (010)              | 1    |
| 6        | OR 1977     | O-RING VITON (014)              | 1    |

B

B



1999A "A" ON LABEL DENOTES CURRENT COIL MFG USING A 1" L PLUNGER

A

A

|   |      |         |  |                |              |
|---|------|---------|--|----------------|--------------|
|   | NAME | DATE    | <b>TEXAS INDUSTRIAL REMCOR, INC.</b>                   |                |              |
| DRAWN   | JAM  | 3/20/20 | TITLE:<br><br><b>1999 REPAIR KIT</b><br>SEE NOTE ABOVE |                |              |
| CHECKED   | JAM  | 3/20/20 |  |                |              |
| ENG APPR.   |      |         |  |                |              |
| MFG APPR.   |      |         |  |                |              |
| <b>PROPRIETARY AND CONFIDENTIAL</b>   |      |         | SIZE   | DWG. NO.       | REV          |
| THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF TEXAS INDUSTRIAL REMCOR, INC. ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT THE WRITTEN PERMISSION OF TEXAS INDUSTRIAL REMCOR, INC. IS PROHIBITED. |      |         | <b>A</b>   | <b>KT 2045</b> | <b>A</b>     |
|   |      |         | SCALE: 1:1   |                | SHEET 1 OF 1 |

2

1